



## **CITY OF MERRITT**

### **2015 MERRITT BRIDGE INSPECTION REPORT**



**Issued: December 15, 2015**

**Prepared by:**

**WATSON ENGINEERING LTD.**

**760 Seymour Street**

**Kamloops, B.C.**

**V2C 2H3**

**Telephone: (250) 374-2244**

**Fax: (250) 374-9292**

**E-Mail: [watson@direct.ca](mailto:watson@direct.ca)**

2015-12-15

1597/4A

City of Merritt  
2185 Voght Street  
Merritt, BC V1K 1B8

Attention: Shawn Boven  
Public Works Manager

**RE: CITY OF MERRITT  
BRIDGE INSPECTION REPORTS**

---

Please find attached our Bridge Inspection Reports for the six bridges in the City of Merritt Bridge Inventory.

Note that these Bridge Inspections are based entirely on Visual Inspection and – as such – can only identify visible defects and deficiencies. Given this Scope of Inspection, these Bridge Inspection Reports cannot be considered completely comprehensive; however, they are intended to provide a representative assessment of the condition of each structure.

Yours truly,  
WATSON ENGINEERING LTD.

  
Andrew D. Watson, P. Eng.  
President

/jgb

Encl.



## **2015 MERRITT BRIDGE INSPECTION REPORT**

### **TABLE OF CONTENTS**

Title Page  
Cover Letter  
Table of Contents

#### **Voght Street Bridge**

Report.....	Section 1, 13 Pages
Photos.....	Section 1, 8 Pages

#### **Houston Truck Bridge**

Report.....	Section 2, 13 Pages
Photos.....	Section 2, 14 Pages

#### **Middlesboro Bridge**

Report.....	Section 3, 14 Pages
Photos.....	Section 3, 11 Pages

#### **Collettville Bridge**

Report .....	Section 4, 12 Pages
Photos.....	Section 4, 9 Pages

#### **Nicola River Pedestrian Bridge**

Report.....	Section 5, 13 Pages
Photos .....	Section 5, 8 Pages

#### **Centennial Park Pedestrian Bridge**

Report .....	Section 6, 13 Pages
Photos .....	Section 6, 8 Pages

**BRIDGE CONDITION SURVEY****Voght Street Bridge****City of Merritt**

---

Municipality:	City of Merritt
Structure:	Voght Street Bridge
Number:	1
Inspector(s):	Stephan Anderson CTech
Inspection Date:	2015 Dec 1
Temperature:	-8 Degrees Celsius

---

**GENERAL DESCRIPTION**

Location:	Voght Street At Nicola River
Crossing Type:	River Crossing
Structure Type:	Prestressed Box Beam Girders
Estimated Traffic:	Residential And Commercial Traffic
Load Rating:	No Restrictions Posted
Clearances:	No Restrictions Posted
Replacement Cost:	\$2,200,000.00

---



---

**BRIDGE CONFIGURATION**

Overall Length:	32.0m
Overall Width:	15.5m
Skew:	20°
No. Of Spans:	Two
Length Of Spans:	16.0m
No. Of Piers:	One
No. Of Abutments:	Two

---

**BRIDGE CROSS SECTION**

Sidewalk/Bicycle Path	
Number:	Two
Width:	2m Sidewalk / 2m Bicycle Path Both Sides.
Vehicle Lanes	
Number:	Two.
Width:	3.6m
Roadway Width:	11.2m

---

**STRUCTURAL HISTORY**

## Original Construction

Engineer:	Watson Engineering Ltd.
Contractor:	Wildstone Construction Ltd.
Design Code:	CSA S6 - 06
Design Vehicle:	CL 625
Year:	2007

## Regular Load Analysis

Rating:	Not Reviewed
Engineer:	
Year:	

## Clause 14 Load Analysis

Rating:	Not Reviewed
Engineer:	
Year:	

---

## ROADWAY INSPECTION

	Observations	Recommendations
<p>Bridge Rail Type:</p> <p>Condition:</p> <p>Bridge Parapet Type: Condition:</p> <p>Pedestrian Rail Type: Height: Condition:</p> <p>Sidewalk/Bicycle Path Location: Type: Condition:</p>	<p>CIP Concrete Pillasters With River Rock Covering And Yellow Cedar Glulam Posts Banded by Powder Coated Black Steel And Copper Sheeting With MoT Steel Rail Powder Coated Black. Steel Posts Support Rail Between Pilasters.</p> <p>Good</p> <p>None.</p> <p>As Bridge Rail</p> <p>Both Sides 2.3m CIP Reinforced Concrete Sidewalk and 2m Asphalt Bicycle Path.</p> <p>Good. Sidewalk Concrete Is Coloured, Stamped And Sealed. Some Surface Spalling On Upstream Sidewalk. Settling of Bridge Approaches Has Caused A 25mm Difference In Elevation Between Approach Sidewalk And Bridge Sidewalk at the NE Corner And A 10mm Difference In Elevation At The NW Corner Which Has Been Previously Ground To Match Sides. The SE and SW Sidewalk / Bridge Joints Are Also Settling Up To 15mm.</p>	<p>Grind Down Bridge SideWalk Concrete To Match Elevation Of Approach Sidewalk Concrete.</p>

**BRIDGE CONDITION SURVEY****Voght Street Bridge****City of Merritt**

Curb	Location: Type: Condition:	Between Sidewalk And Bicycle Path CIP Concrete Good.	Continue Program.	Crack	Sealing
Wearing Surface	Type: Condition:	102mm Thick Asphalt On Membrane Fair. Surface Is Showing Signs Of Wear With Wheel Path Groves Appearing Since Last Inspection.			
End Joints	Type: Condition:	None. Settlement Of Bridge Approaches Has Caused Elevation Change At North End With Corresponding Cracking In Asphalt Road Surface And Slight Bump In Travelled Surface. Cracks are Sealed.			
Intermediate Fixed Joints	Location: Type: Condition:	None.			
Intermediate Expansion Joints	Location: Type: Condition:	None.			
Deck Drains/Scuppers	Type: Condition:	None.			

## SUPERSTRUCTURE INSPECTION

	Observations	Recommendations
Deck Type: Condition:	Concrete Box Beam Surface New in 2008. Not Accessible For Inspection.	
Girders Type: Number: Depth: Condition:	Prestressed Concrete Box Beams Twenty-Six 700mm Good.	
Diaphragms Location: Type: Condition:	None.	
Bearings Location: Type: Condition:	Abutments (Expansion) And Pier (Fixed). 20mm Rubber Bearing Pads And Galvanized Steel Pins. Good.	

## ABUTMENT AND PIER INSPECTION

	Observations	Recommendations
Bearing Pedestal Type: Condition:	CIP Concrete Beam Seat At Top Of Ballast Wall. Good.	
Ballast Wall Type: Condition:	CIP Concrete. Good.	
Base Type: Condition:	None.	
Foundation Type: Number: Condition:	Steel Piling 11 Not Accessible For Inspection.	
Wing Walls Type: Condition: Guardrail:	CIP Concrete. Good. Modified MoT Steel Guardrail, Powder Coated Black	

**BRIDGE CONDITION SURVEY****Voght Street Bridge****City of Merritt**

<p>Pier</p> <p>Type: Condition: Foundation:</p> <p>Slope Protection</p> <p>Location: Type: Condition:</p> <p>Waterway Channel</p> <p>Alignment: Flow:</p> <p>Stability:</p>	<p>CIP Concrete Pile Cap. Good. Steel Piling With Black Epoxy Coating On Exposed Lengths. Epoxy Coating Has Peeled Off In Various Sections On Exposed Areas.</p> <p>Upstream, Downstream And At Abutments. Rip Rap. Good</p> <p>Good. Moderately High Water With Ice At The Time Of Inspection. No Issues Found. Good.</p>	<p>Recoat With Black Epoxy During Low Water Level.</p>
---	--	--

## APPROACH INSPECTION

	Observations	Recommendations
<p>Alignment</p> <p>Horizontal:</p> <p>Vertical:</p>	<p>Slight Horizontal Curve.</p> <p>Crest Of Vertical Curve With 1.1m Rise To Bridge Deck From South At Merritt Ave. And From North At Second Avenue.</p>	
<p>Guardrail</p> <p>Location:</p> <p>Type:</p> <p>Condition:</p>	<p>None.</p>	
<p>Barrier</p> <p>Location:</p> <p>Type:</p> <p>Condition:</p>	<p>None.</p>	
<p>Sidewalk/Bicycle Path</p> <p>Location:</p> <p>Type:</p> <p>Condition:</p>	<p>Both Sides From Merritt Avenue To Bridge And From Bridge To Second Avenue.</p> <p>CIP Concrete Sidewalk and 2m Asphalt Bicycle Path.</p> <p>Good. Sidewalk Concrete Is Coloured, Stamped And Sealed.</p>	
<p>Curbs</p> <p>Location:</p> <p>Type:</p> <p>Condition:</p>	<p>Both Sides From Merritt Avenue To Bridge And From Bridge To Second Avenue.</p> <p>CIP Concrete.</p> <p>Good.</p>	



**BRIDGE CONDITION SURVEY****Voght Street Bridge****City of Merritt**

Roadway Type: Condition:	Asphalt. Fair. Surface Is Showing Signs Of Wear With Wheel Path Groves Appearing Since Last Inspection.	
Roadway End Joint Type: Condition:	None.	
Approach Slabs Type: Condition:	None.	
Approach Embankment Type: Condition:	None.	
Drainage Type: Condition:	CB's Near Merritt Avenue Otherwise Surface Drainage Only.  Good.	
Abutment Fencing Type: Condition:	Modified MoT Steel Guardrail, Powder Coated Black. Good. Steel Railing Post Base Plates Are Corroding, Possibly Due To Road Salt Accumulation During Winter Months.	Remove Corrosion And Paint Baseplates

## LIGHTING, ELECTRICAL AND SIGN INSPECTION

	Observations	Recommendations
Lamp Standards Type: Number: Condition:	Decorative Glulamated Timber. 8 Good. 2 Acorn Nuts Are Missing From The NW Corner Post Base	
Wiring & Junctions Condition:	2 Buried Conduits From Centennial Park Washroom Bldg. To Northeast Wingwall With Junction Box In Lawn Off Park. Lighting Conduit Has Junction At Northeast Pilaster Wood Post To Light East Side and Buried Conduit Continues Across Roadway To West Side Lighting. Waterline Heat Trace Follows Same Path To North West Manhole And Continues To South End Of Waterline At South Abutment.	
Signs Type: Number: Condition:	None.	

## UTILITIES INSPECTION

	Observations	Recommendations
Utilities Over Bridge BC Hydro: BC Tel: Other:	East Side. West Side. None.	
Utilities On Bridge BC Hydro: BC Tel: BC Gas: Water: Sanitary: Sewer: Other:	Over None. East Side. West Side. None. None. None.	
Utilities Adjacent To Bridge BC Hydro: BC Tel: BC Gas: Water: Sanitary Sewer: Storm Sewer: Other:	None. None. None. None. None. Upstream End Of South Abutment Unknown.	

## RECOMMENDED MAINTENANCE AND REPAIRS

Item	Approved		Completed		Description	Comments
	Initial	Date	Initial	Date		
1					Bridge Approach Settlement Has Caused Asphalt Road Surface And Concrete Sidewalk Surface Elevation Differences At The Bridge End Joints.	Grind Concrete Sidewalk To Remove Lip To Match Elevations For Smooth Pedestrian Use And Continue Sealing Cracks In Asphalt At Bridge End Joints.
2					Steel Railing Base Plates.	Require Corrosion Removal And Re- Painting.
3					Concrete Surface Spalling on Upstream Sidewalk In Approximately 3m <sup>2</sup> Area.	Repairs Not Required, Does Not Affect Usage Of Sidewalk.
4					Steel Piling With Black Epoxy Coating On Exposed Lengths. Epoxy Coating Has Peeled Off In Various Sections On Exposed Areas.	Require Corrosion Removal And Re- Painting.

## ENGINEER'S COMMENTS

This structure was constructed in 2006 and is in good structural condition with a few minor maintenance items.



Photo #01. View Of Structure From North Approach.




Photo #02. View Of Structure From South Approach.





Photo #03. View Of Structure From West Bank Upstream.



Photo #04. View Of Structure From West Bank Downstream.





Photo #05. View Upstream.



Photo #06. View Downstream.



Photo #7. Rip Rap On East Abutment.



Photo #8. Rip Rap On West Abutment.





Photo #9. Gasline On South Side.



Photo #10. Waterline On North Side.





Photo #11. 10 - 25mm Settlement Of Concrete Sidewalk On Bridge Approaches.



Photo #12. Asphalt Cracking And Settlement At North Abutment.





Photo #13. Surface Spalling Of Sidewalk Concrete.



Photo #14. Railing Baseplate Corrosion.





Photo #15. Pier Piles With Peeling Paint And Corrosion.



Photo #16. Asphalt Cracking And Settlement At South Abutment.



**BRIDGE CONDITION SURVEY****Houston Truck Bridge****City of Merritt**

---

---

Municipality:	City Of Merritt
Structure:	Houston Truck Bridge
Number:	2
Inspector(s):	Stephan Anderson, CTech.
Inspection Date:	2015 Dec 1
Temperature:	- 8 Degrees Celsius

---

**GENERAL DESCRIPTION**

Location:	Houston Street At Coldwater River
Crossing Type:	River Crossing
Structure Type:	Steel Girder With Precast Deck Panels.
Estimated Traffic:	Residential And Commercial Truck Traffic.
Load Rating:	No Restrictions Posted
Clearances:	No Restrictions Posted
Replacement Cost:	\$3,000,000.00

---

**BRIDGE CONFIGURATION**

Overall Length:	51.818m
Overall Width:	12.73m
Skew:	25 Degrees
No. Of Spans:	One
Length Of Spans:	51.818m
No. Of Piers:	None
No. Of Abutments:	Two

---

**BRIDGE CROSS SECTION**

Sidewalk/Bicycle Path	
Number:	One.
Width:	1m - 1.5m Approximately.
Vehicle Lanes	
Number:	Two
Width:	5.1m
Roadway Width:	10.2m

---

**STRUCTURAL HISTORY**

## Original Construction

Engineer:	Associated Engineering Ltd.	
Contractor:	Surespan Construction Ltd.	
Design Code:	CAN/CSA - S6 - 88	
Design Vehicle:	CS - 600	
Year:		1998

## Slope Stabilization

Engineer:	Watson Engineering Ltd.	
Contractor:	LNB Construction Ltd.	
Design Code:		
Design Vehicle:		
Year:		2013

## Regular Load Analysis

Rating:	Not Reviewed	
Engineer:		
Year:		

## Clause 12 Load Analysis

Rating:	Not Reviewed	
Engineer:		
Year:		

---



## ROADWAY INSPECTION

	Observations	Recommendations
Bridge Rail Type: Condition:	Standard MoT Steel Rail Good.	
Bridge Parapet Type: Condition:	CIP Reinforced Concrete. Good	
Pedestrian Rail Type: Height: Condition:	Standard MoT Pedestrian Fence. 1.22m. Good.	
Sidewalk/Bicycle Path Location: Type: Condition:	Upstream Side. Precast Concrete Panels. Good.	
Curb Location: Type: Condition:	None.	

**BRIDGE CONDITION SURVEY****Houston Truck Bridge****City of Merritt**

Wearing Surface Type: Condition:	Asphalt With Membrane. Fair. Some Cracking	
End Joints Type: Condition:	None. Asphalt Is Cracked At The Abutments With Some Settling Of Bridge End Fills. South Approach Roadway Has Settled A Large Amount.	Consider Rebuilding Approaches At Abutments With Properly Compacted Base Materials And Asphalt.
Intermediate Fixed Joints Location: Type: Condition:	None.	
Intermediate Expansion Joints Location: Type: Condition:	None.	
Deck Drains/Scuppers Type: Condition:	None Installed But Drainage Design Required. Some Runoff Drains Out Onto Downstream Retaining Walls At Ballast Wall At Bridge End Joint. Drainage Is Causing Material To Accumulate And Push Against The Chain Link Fence On Top Of The MSE Wall	Remove Accumulated Slope Material Against Chain Link Fencing At All Four Wing Walls And Provide Alternative Slope Design To Eliminate Re-Occurance.

## SUPERSTRUCTURE INSPECTION

	Observations	Recommendations
Deck Type: Condition:	Concrete Precast Panel Surface. Not Accessible For Inspection Due To Asphalt Surface Other Than Sidewalk Surface Which Is In Good Condition.	
Girders Type: Number: Depth: Condition:	Steel Plate Girders. Two 2470mm Good. Graffiti	
Diaphragms Location: Type: Condition:	Every Five Metres Steel Angles Good. Construction Cables Attached To Diaphragms Hang Down To Within Reachable Distance From River Bank.	Remove Unnecessary Construction Cables Attached To Diaphragms.
Bearings Location: Type: Condition:	Abutments. Elastomeric Pot Bearing. Good.	

## ABUTMENT INSPECTION

	Observations	Recommendations
Bearing Pedestal Type: Condition:	CIP Concrete Beam Seat. Good. Grafitti	
Ballast Wall Type: Condition:	CIP Concrete cast Onto Steel Girder Ends. Good. Grafitti.	
Base Type: Condition:	CIP Concrete With Unknown Foundation Behind Mechanically Stabalized Earth Wall (MSE). Good.	
Foundation Type: Footing:	Unknown. Not Accessible For Inspection.	
Wing Walls Type: Condition:	CIP Concrete. Good. Drainage And Foot Traffic Causing Material On Slope Adjacent To Wing Walls To Accumulate And Push Against Chain Link Fence.	
MSE Walls  Condition:	Mechanically Stabilized Earth Wall with Precast Concrete Panels Attached To Galvanized Steel Mesh Anchor Mats Layered Under Approach Fill And Bridge End Fill. Good. All Surface Areas Vertical. No Movement Or Miss-Alignment Detected. Grafitti.	

**BRIDGE CONDITION SURVEY****Houston Truck Bridge****City of Merritt**

<p>Slope Protection</p> <p>Location:</p> <p>Type:</p> <p>Condition:</p> <p>Waterway Channel</p> <p>Alignment:</p> <p>Flow:</p> <p>Stability:</p>	<p>Upstream, Under And Downstream Of MSE Walls.</p> <p>Rip Rap.</p> <p>Good</p> <p>Slight Skew</p> <p>River Covered In Ice At Time Of Inspection.</p> <p>Good.</p>	
---	---	--

## APPROACH INSPECTION

	Observations	Recommendations
Alignment Horizontal: Vertical:	On Tangent between Curves. Constant Grade.	
Guardrail Location: Type: Condition:	None.	
Barrier Location: Type: Condition:	On Both Approaches. Concrete Roadside Barrier. Good.	
Sidewalk/Bicycle Path Location: Type: Condition:	Upstream Side. Road Gravels Fair.	
Curbs Location: Type: Condition:	None.	

**BRIDGE CONDITION SURVEY****Houston Truck Bridge****City of Merritt**

Roadway Type: Condition:	Asphalt. Good.	
Roadway End Joint Type: Condition:	None.	
Approach Slabs Type: Condition:	None.	
Approach Embankment Type: Condition:	Earthwork Good.	
Drainage Type:  Condition:	2 Catch Basins Located South Of Downstream South Abutment and 2 North of Downstream North Abutment And At The End Of Downstream North Approach Flare. Good Structurally, However, Are Poorly Draining As They Appear To Fill Rapidly With Debris And Block Flow Of Drainage Water.	Clean And Maintain Catch Basins On A Regular Basis To Provide Adequate Drainage And Prevent Slope Failure Due To Overflow.
Abutment Fencing Type: Condition:	Chain Link. Poor. Chain Link Gates Open And Damaged Chainlink/Barbed Wire On Both Sides.	Repair Existing And/Or Enhance To Deter Access To This Area for Safety Reasons As Well As To Protect Bridge And Utilities From Vandalism.

## LIGHTING, ELECTRICAL AND SIGN INSPECTION

	Observations	Recommendations
Lamp Standards Number: Type: Condition:	Two. At Abutments. Unknown. Good.	
Wiring & Junctions Condition:	Appear In Fair Condition, Junction Boxes And Wiring Located On The Upstream North Abutment For Heat Trace To Sanitary And Waterline. Covered In Grafitti	Remove Grafitti And Check Condition.
Signs Condition:	Reflective W-36 Warning Signs Are Installed At All Four Corners Of The Bridge At The Abutments. The South Abutment W-36 Signs Have Been Bent Over But Remain Servicable. The No Stopping On Bridge Sign At The Upstream South Approach Is Missing	Replace No Stopping Sign At Upstream South Approach.



## UTILITIES INSPECTION

	Observations	Recommendations
Utilities Over Bridge BC Hydro: BC Tel: Other:	None. None. Unknown.	
Utilities On Bridge BC Hydro: BC Tel: BC Gas: Water: Sanitary: Sewer: Other:	None. None. None. Insulated Waterline Attached On East Side. Insulated Sanitary Line Attached On East Side. None. None.	Taped Joints Deteriorating Taped Joints Deteriorating
Utilities Adjacent To Bridge BC Hydro: BC Tel: BC Gas: Water: Sanitary Sewer: Storm Sewer: Other:	Unknown. Unknown. Unknown. Unknown. Unknown. Unknown. Unknown.	

## RECOMMENDED MAINTENANCE AND REPAIRS

Item	Approved		Completed		Description	Comments
	Initial	Date	Initial	Date		
1					The No Stopping On Bridge Sign At The Upstream South Approach Is Faded.	Replace No Stopping Sign At Upstream South Approach.
2					Drainage At All Four Wing Walls Is Causing Slope Material To Build Up Against Chain Link Fencing Which Is Bent And Compromised Out And Over The Top Of The MSE Wall.	Remove Accumulated Slope Material Against Chain Link Fencing At All Four Wing Walls And Provide Alternative Slope Design To Eliminate Re-Occurance.
3					Construction Cables Hanging From Bridge Girders To A Reachable Height From River Bank.	Remove Cables.
4					Chainlink Fencing At Abutment Is Damaged / Vandalized.	Repair / Enhance Existing Fence To Deter Access To Abutment for Safety Reasons As Well As To Protect Utilities From Vandalism.

## ENGINEER'S COMMENTS

The overall structure is in good condition. The South Approach downstream slope was repaired in 2013 and remains in good condition. There is a tendency for road debris to accumulate on the roadway side of all barriers causing drainage problems as the catch basins fill. The roadway should be cleaned periodically. The slopes adjacent to the wing walls are eroding and accumulating and pushing against the chain link fence on top of the MSE wall. There is vandalism damage to the chain link fencing at the abutments and bearings allowing access to the bearing seats and top of MSE wall. This poses a potential liability as there is a long drop from the bearings to the rip rap below with risk of injury. The amount and location of graffiti has increased dramatically since the 2008 inspection. Some graffiti is located on the steel girders in mid bridge span.



Photo #01. View Of Structure From North Approach.



Photo #02. View Of Structure From South Approach.





Photo #03. View Of Structure From West Bank Upstream.



Photo #04. View Of Structure From West Bank Downstream.





Photo #05. View Upstream.



Photo #06. View Downstream.





Photo #07. South Abutment Joint.



Photo #08. North Abutment Joint.



Photo #09. North Abutment And MSE Wall.



Photo #10. South Abutment And MSE Wall. Note Steel Diaphragms And Graffiti.





Photo #11. South Abutment Bearing Seat.



Photo #12. North Abutment Bearing Seat. Note Graffiti.





Photo #13. Steel Girders And Precast Concrete Deck Panels.



Photo #14. Detail Of Steel Girder, Steel Diaphragm And Underside Of Precast Concrete Deck Panels. Note: Cable.



Photo #15 Downstream Parapet And Railing From South Abutment.



Photo #16. Upstream Parapet And Pedestrian Railing From South Abutment.





Photo #17. Utilities At Upstream North Abutment. Note Fencing Damaged.



Photo #18. Upstream North Abutment. Note Gate Open.





Photo #19. South Bank. Note: Cables Within Reach From Ground.



Photo #20. Upstream South Abutment. Note: Gate Open.





Photo #21. Fencing At Downstream South Abutment. Note: Runoff Debris Accumulating Against Fence.



Photo #22. W-36 Signs At South Abutment. Note: Damage To Sign Mounts.





Photo #23. Downstream North Approach. Note: Accumulated Road Debris And Choked Catch Basin.



Photo #24. Downstream South Approach Drain Pipe.





Photo #25. Downstream South Approach Catch Basin. Note: Found Filled With Debris.




Photo #26 Downstream South Approach Drainage.





Photo #27 Culverts Under Downstream North Approach Fill.



Photo #28 Culverts Under Upstream North Approach Fill.





**BRIDGE CONDITION SURVEY****Middlesboro Bridge****City of Merritt**

---

Municipality:	City of Merritt
Structure:	Middlesboro Bridge
Number:	3
Inspector(s):	Stephan Anderson CTech.
Inspection Date:	2015 Dec 1
Temperature:	- 6 Degrees Celsius

---

**GENERAL DESCRIPTION**

Location:	Voght Street At Coldwater River.
Crossing Type:	River Crossing
Structure Type:	Multiple Concrete Stringers With Concrete Deck
Estimated Traffic:	Local Residential, Commercial And Industrial Traffic
Load Rating:	No Restrictions Posted
Clearances:	No Restrictions Posted
Replacement Cost:	\$2,500,000.00

---

**BRIDGE CONFIGURATION**

Overall Length:	58.52m
Overall Width:	9.6m
Skew:	None.
No. Of Spans:	Two
Length Of Spans:	29.26m
No. Of Piers:	One
No. Of Abutments:	Two

---

**BRIDGE CROSS SECTION**

Sidewalk/Bicycle Path	
Number:	One
Width:	1.62m
Vehicle Lanes	
Number:	Two
Width:	3.65m
Roadway Width:	7.32m

---

**STRUCTURAL HISTORY**

## Original Construction

Engineer:	Department Of Highways Bridge Office
Contractor:	Not Available
Design Code:	AASHTO (1969)
Design Vehicle:	H25 520
Year:	1970

## Regular Load Analysis

Rating:	Not Reviewed
Engineer:	
Year:	

## Clause 12 Load Analysis

Rating:	Not Reviewed
Engineer:	
Year:	

---

## ROADWAY INSPECTION

	Observations	Recommendations
Bridge Rail Type:  Condition:	Steel Post Anchored To CIP Bridge Deck With Three Tubular HSS Rails. Fair, Three Posts Bent From Vehicle Collision Still Bolted To Deck, Four Missing Post To Rail Clamps, Galvanizing Worn Off On Two Rails North East Corner.	Straighten Posts And Repair As Necessary. Replace Missing Clamp, Prepare Surface And Paint With Zinc Rich Paint To Avoid Further Corrosion Of Railing.
Bridge Parapet Type: Condition:	None.	
Pedestrian Rail Type: Height: Condition:	As Bridge Railing.	
Sidewalk/Bicycle Path Location: Type: Condition:	Upstream Side. CIP Concrete. Good.	
Curb Location: Type: Condition:	Both Sides. CIP Concrete. Good.	

**BRIDGE CONDITION SURVEY****Middlesboro Bridge****City of Merritt**

Wearing Surface Type: Condition:	Concrete. Fair.	
End Joints Type: Condition:	Fixed.	
Intermediate Fixed Joints Location: Type: Condition:	None.	
Intermediate Expansion Joints Location: Type: Condition:	None.	
Deck Drains/Scuppers Type: Condition:	None.	



## SUPERSTRUCTURE INSPECTION

	Observations	Recommendations
Deck Type: Condition:	CIP Reinforced Concrete. Good.	
Girders Type: Number: Depth: Condition:	Precast Prestressed Concrete I-Girders. Eight 1.472m Deep x 0.609m Wide Flanges. Good. Some Graffiti Near Abutments.	
Diaphragms Location: Type: Condition:	Quarter Points. Steel L-Shapes. Good.	
Bearings Location: Type: Condition:	Abutments. Neoprene Rubber Pads Good.	

## ABUTMENT INSPECTION

	Observations	Recommendations
Bearing Pedestal Type: Condition:	CIP Concrete Beam Seat. Good. Note Graffiti On Abutment Walls.	
Ballast Wall Type: Condition:	CIP Concrete. Good. Ballast Walls Are Cast Into The Ends Of The Bridge Concrete Girders And Are Under The Influence Of The Expansion And Contraction Forces Associated With The Girders. This Has Been Found To Cause The Ballast Walls To Move Slightly In Relation To The Bridge End Fill In Other Bridges With The Same Feature. This May Be The Cause For The Asphalt Roadway Surface Failures Adjacent To The Bridge Deck. Note Graffiti On Abutment Walls.	
Base Type: Condition:	CIP Concrete Beam Seat. Good.	
Foundation Type: Footing:	CIP Concrete Footing Not Accessible For Inspection.	

**BRIDGE CONDITION SURVEY****Middlesboro Bridge****City of Merritt**

Wing Walls Type: Condition:	CIP Concrete. Good. Graffiti Covered.	
Slope Protection Location: Type:  Condition:	Upstream And Downstream Of Abutments. Riverbed Materials With Natural Vegetation. Rip Rap Was Initially Placed To High Water Elevation But Is Now Buried.  Fair To Good.	
Waterway Channel Alignment:  Flow: Stability:	30 Degree Skew To Bridge From Upstream. Perpendicular Downstream. Moderately High With Ice At The Time Of Inspection. Unknown. Pier Should Be Inspected For Scour	Inspect Riverbed Surrounding The Pier For Scour.

## PIER INSPECTION

	Observations	Recommendations
<p>Bearings Location: Type: Condition:</p> <p>Base Type: Condition:</p> <p>Foundation Type: Footing:</p> <p>Waterway Channel Alignment:</p> <p>Flow: Stability:</p>	<p>Pier At Mid Span. Neoprene Rubber Pads Not Accessible For Hands-On Inspection, However, Appears To Be In Good Condition.</p> <p>CIP Concrete Good</p> <p>Steel H Piles Not Accessible For Inspection.</p> <p>30 Degree Skew To Bridge From Upstream. Perpendicular Downstream. Moderate High With Ice At The Time Of Inspection. Unknown. Pier Should Be Inspected For Scour</p>	<p>Inspect Riverbed Surrounding The Pier For Scour.</p>

## APPROACH INSPECTION

	Observations	Recommendations
<p>Alignment Horizontal: Vertical:</p> <p>Guardrail Location: Type: Condition:</p> <p>Barrier Location: Type: Condition:</p> <p>Sidewalk/Bicycle Path Location: Type: Condition:</p>	<p>Relatively Straight With Good Visibility. Relatively Flat With Good Visibility.</p> <p>None.</p> <p>Both Sides Of Both Approaches. Concrete Roadside Barrier. Fair To Poor. One Bullnose Is Missing And One Is Out Of Place. The South West CRB At The Abutment Wall Is Sagging Due To Loss Of Supporting Gravel Materials Underneath.</p> <p>East Side Gravel Shoulder Poor. Sidewalk Slopes Sideways And Steps Up To Bridge Deck Which Presents A Trip Hazard And Makes It Difficult For Wheel Chair Access. This Presents A Considerable Liability Issue And Should Be Addressed.</p>	<p>Replace Bullnose, Reposition Bullnose, Repair South West CRB By Replacing Supporting Materials And Repositioning.</p> <p>Consider Upgrading Approach Sidewalk To Prevent Liability Issue.</p>

**BRIDGE CONDITION SURVEY****Middlesboro Bridge****City of Merritt**

Curbs Location: Type: Condition:	None.	
Roadway Type: Condition:	Asphalt. Fair . Asphalt Is Cracked And Potholes Have Formed With Some Potholes Being Patched At Abutments.	
Roadway End Joint Type: Condition:	None.	
Approach Slabs Type: Condition:	None.	
Approach Embankment Type: Condition:	Fill Fair To Poor. Replace Materials On South West Abutment.	Repair South West CRB By Replacing Supporting Materials And Repositioning.
Drainage Type: Condition:	Natural. Fair To Poor. Water Drainage Appears To Be The Cause Of The Loss Of Materials On The South West Abutment.	Repair South West CRB By Replacing Supporting Materials And Repositioning. Consider Adding Asphalt Curb To Move Drainage Further From Abutment.
Abutment Fencing Type: Condition:	None.	



## LIGHTING, ELECTRICAL AND SIGN INSPECTION

	Observations	Recommendations
Lamp Standards Number: Type: Condition:	None. None. None.	
Wiring & Junctions Condition:	None.	
Signs Condition:	Warning Markers At Abutments.	

## UTILITIES INSPECTION

	Observations	Recommendations
Utilities Over Bridge BC Hydro: BC Tel: Other:	None. None. Unknown.	
Utilities On Bridge BC Hydro: BC Tel: BC Gas: Water: Sanitary: Sewer: Other:	None. None. 6" Gasline Attached To Inside Of Downstream Stringer. None. None. None. None.	
Utilities Adjacent To Bridge BC Hydro: BC Tel: BC Gas: Water: Sanitary Sewer: Storm Sewer: Other:	Approximately 10m East Of Bridge. Unknown. Unknown. Unknown. Unknown. Unknown. Unknown.	

## RECOMMENDED MAINTENANCE AND REPAIRS

Item	Approved		Completed		Description	Comments
	Initial	Date	Initial	Date		
1					Repair / Reposition Bent Railing Posts.	Repair / Reposition Bent Railing Posts.
2					Corrosion Of Guard Rail.	Clean And Coat Corroded Railing With Zinc Rich Paint.
3					CRB Displaced And Out Of Alignment Due To Settlement Of Supporting Materials.	Repair South West CRB By Replacing Supporting Materials And Repositioning. Consider Adding Asphalt Curb To Move Drainage Away From Abutment.
4					Approach Sidewalk In Poor Condition And Present Liability Issues.	Rebuild Approach Sidewalks.
5					South Bullnose Barriers Displaced.	Replace Concrete Bullnose Barriers.
6					Four Missing Railing To Post Bolts	Replace Railing To Post Bolts.
7					Unknown River Bed Condition At Centre Pier	Consider Scour Inspection Of Centre Pier.

## ENGINEER'S COMMENTS

This structure is in good condition with some minor repairs required. The Approach Sidewalk Requires Attention.



Photo #01. View Of Structure From East Approach.



Photo #02. View Of Structure From West Approach.





Photo #03. View Of Structure From East Bank Downstream.



Photo #04. View Of Structure From West Bank Downstream.





Photo #05. View Upstream.



Photo #06. View Downstream.





Photo #07. West Abutment Joint.



Photo #08. West Abutment Joint.





Photo #09. Downstream Girders And East Abutment With Gasline.



Photo #10. Girders And West Abutment.





Photo #11. Centre Pier From East Abutment.



Photo #12. Centre Pier And Girders From West Abutment.



Photo #13. Steel Diaphragms.



Photo #14 Sidewalk On Bridge.





Photo #15. Barriers At West Abutment. Note Erosion Of Slope Materials.



Photo #16 Displaced Concrete Barrier Bullnose On Upstream West Approach.





Photo #17. Miss-Aligned Concrete Barrier Bullnose On Downstream West Approach.



Photo #18. Railing At Upstream West Abutment. Note: Bent Post





Photo #19. Railing At Downstream East Abutment. Note: Corroded Rails.



Photo #20 Railing Post Clamps Missing Upstream And Downstream Side.



Photo #21 East Abutment. Note: Material Accumulating Close To Girder.



Photo #22 Centre Pier Joint. Note: Leakage And Corrosion At Joint.



**BRIDGE CONDITION SURVEY****Collettsville Bridge****City of Merritt**

---

---

Municipality:	City of Merritt
Structure:	Collettsville Bridge
Number:	4
Inspector(s):	Stephan Anderson CTech.
Inspection Date:	2015 Dec 1
Temperature:	- 8 Degrees Celsius

---

**GENERAL DESCRIPTION**

Location:	Main Street At Coldwater River
Crossing Type:	River Crossing
Structure Type:	500mm Prestressed Concrete Box Girders On Either End Of 1300mm Prestressed Concrete Box Girders With Cross- Sectional Post Tension Strands.
Estimated Traffic:	Local Residential, Commercial And Industrial Traffic
Load Rating:	No Restrictions Posted
Clearances:	No Restrictions Posted
Replacement Cost:	\$2,500,000.00

---



**BRIDGE CONFIGURATION**

Overall Length:	46.748m
Overall Width:	12.189m
Skew:	10 Degrees
No. Of Spans:	Three
Length Of Spans:	Two @ 8.365m, One @ 30.018m
No. Of Piers:	Two
No. Of Abutments:	Two

---

**BRIDGE CROSS SECTION**

Sidewalk/Bicycle Path	
Number:	One
Width:	1.5m
Vehicle Lanes	
Number:	Two
Width:	4.880m, 4.865m
Roadway Width:	9.745m

---

**STRUCTURAL HISTORY**

## Original Construction

Engineer:	MoT Bridge Engineering
Contractor:	Not Available
Design Code:	CAN/CSA-S6-88
Design Vehicle:	CS-600
Year:	1995

## Regular Load Analysis

Rating:	Not Reviewed
Engineer:	
Year:	

## Clause 12 Load Analysis

Rating:	Not Reviewed
Engineer:	
Year:	

---

## ROADWAY INSPECTION

	Observations	Recommendations
Bridge Rail Type: Condition:	MoT Standard Steel Parapet Railing. Good.	
Bridge Parapet Type: Condition:	CIP Concrete MoT Spec. Good. Original Sealed Expansion Joints Deteriorating.	Re-Seal Expansion Joints.
Pedestrian Rail Type: Height: Condition:	MoT Standard Steel Sidewalk Fence. 1.2m Good. Railing Base Broken Off At SW Wing Wall. Repaired.	
Sidewalk/Bicycle Path Location: Type: Condition:	Upstream Side Asphalt. Good. Settlement At Both Ends Creating Elevation Difference Between Approach And Bridge Deck.	
Curb Location: Type: Condition:	None.	

**BRIDGE CONDITION SURVEY****Collettville Bridge****City of Merritt**

Wearing Surface Type: Condition:	Asphalt. Fair. Cracked At Abutments And Piers. Missing Asphalt Has Been Patched.	Monitor Joints And Replace Asphalt As Required.
End Joints Type: Condition:	None. Fair. Cracked At Abutments And Piers. Missing Asphalt Has Been Patched.	Monitor Joints And Replace Asphalt As Required.
Intermediate Fixed Joints Location: Type: Condition:	At Piers. None. Cracked, Missing Asphalt Has Been Replaced.	Monitor Joints And Replace Asphalt As Required.
Intermediate Expansion Joints Location: Type: Condition:	None.	
Deck Drains/Scuppers Type: Condition:	Galvanized Steel Drain Through 550 Box Girder Near Upstream Piers. Good.	

## SUPERSTRUCTURE INSPECTION

	Observations	Recommendations
Deck Type: Condition:	Concrete. Not Accessible For Inspection.	
Approach Span Girders Type: Number: Depth: Condition:	Prestressed Concrete Box Girders. Twenty 550mm Good. Concrete On Upper Corner Of West Pier Downstream Approach Girder Has Broken Off With Pieces Lying On Top Of Pier Cap. Reinforcing Steel Not Exposed. Reason Unknown.	Monitor For Corrosion Of Box Girder Reinforcing Steel.
Mid Span Girders Type: Number: Depth: Condition:	Prestressed Concrete Box Girders With Cross-Sectional Post Tension Strands. Ten 1300mm Good.	
Diaphragms Location: Type: Condition:	None.	
Bearings Location: Type: Condition:	Abutments And Piers. 20-25mm Natural Rubber Bearing Pads With 25-30mmØ Galvanized Steel Dowels. Good.	

## ABUTMENT INSPECTION

	Observations	Recommendations
Bearing Pedestal Type: Condition:	CIP Concrete Beam Seat. Good.	
Ballast Wall Type: Condition:	CIP Concrete. Good.	
Base Type: Condition:	CIP Concrete Beam Seat. Good.	
Foundation Type: Footing:	Steel Piled Foundation. Not Accessible For Inspection.	
Wing Walls Type: Condition:	CIP Concrete. Good. Damage To SW Wing Wall Due To Railing Anchor Bolt. Concrete Broken Out.	
Slope Protection Location: Type: Condition:	Upstream And Downstream Of Abutments. Rip Rap. Fair To Good.	
Waterway Channel Alignment: Flow: Stability:	Straight. Approaching High Water At Time Of Inspection. Good.	



## APPROACH INSPECTION

	Observations	Recommendations
Alignment Horizontal: Vertical:	Relatively Straight With Good Visibility. Relatively Flat With Good Visibility From West End. Up Grade To Match Bridge Deck From East End.	
Guardrail Location: Type: Condition:	None.	
Barrier Location: Type: Condition:	Both Approaches. Concrete Roadside Barrier. Good Condition	
Sidewalk/Bicycle Path Location: Type: Condition:	Upstream/South Side. Asphalt. Fair. SW End Appears To Have Been Filled In Since 2008 Inspection, However Material Continues To Be Removed By Pedestrian Traffic.	Build Up This Area Further To Eliminate Slope Which Starts At Edge Of Asphalt Sidewalk.

**BRIDGE CONDITION SURVEY****Collettville Bridge****City of Merritt**

Curbs Location: Type: Condition:	Both Approaches Short Concrete Curb And Platform On Which The Concrete Barriers Are Placed. Good.	
Roadway Type: Condition:	Asphalt. Fair.	
Roadway End Joint Type: Condition:	None. Asphalt Is Cracked, Missing Asphalt Has Been Replaced And Cracks Sealed.	Monitor Joints And Replace Asphalt And Seal Joints As Required.
Approach Slabs Type: Condition:	None.	
Approach Embankment Type: Condition:	None.	
Drainage Type: Condition:	Drains On Road Side Of Barriers On Upstream Abutment Side Of Piers. Good. Appear To Function.	
Abutment Fencing Type: Condition:	None.	

## LIGHTING, ELECTRICAL AND SIGN INSPECTION

	Observations	Recommendations
Lamp Standards Number: Type: Condition:	None.	
Wiring & Junctions Condition:	Good. In Ground Junction Box Is On North East Abutment Slope.	
Signs Condition:	Good.	

## UTILITIES INSPECTION

	Observations	Recommendations
Utilities Over Bridge BC Hydro: BC Tel: Other:	Overhead On South Side. Overhead On South Side. Unknown.	
Utilities On Bridge BC Hydro: BC Tel: BC Gas: Water:  Sanitary: Sewer: Other:	None. None. None. Insulated Waterline On North Side. Insulation Steel Covering Requires Joint Repair At Exposed Pipe Joint Near Centreline.  Insulated Forcemain On North Side. None. Junction Box For Unknown Utility Service.	Re-Seal Insulation Joint And Repair Exposed Insulation At One Pipe Joint.
Utilities Adjacent To Bridge BC Hydro: BC Tel: BC Gas: Water: Sanitary Sewer: Storm Sewer: Other:	Unknown. Unknown. Gas Line Underground 5m Downstream Of Bridge Unknown. Unknown. Unknown. Junction Box For Heat Trace On North East Approach Embankment. Junction Box For Unknown Utility Attached To North West Side Of Concrete Box Girder has Open Conduit.	Repair Open Conduit.



## RECOMMENDED MAINTENANCE AND REPAIRS

Item	Approved		Completed		Description	Comments
	Initial	Date	Initial	Date		
1					Asphalt Wearing Surface Is Cracked At Joints. Missing Asphalt Has Been Replaced/Patched.	Continue Monitoring And Replace Asphalt As Required.
2					Upstream West Side Requires Repair To Undermined Asphalt Sidewalk At Abutment.	Eroded Material Had Been Replaced With WGB Gravel Since 2008 Inspection, However, Pedestrian Traffic Continues To Increase Erosion In This Spot. Consider Placing A Larger Quantity Of WGB To Reduce Slope Adjacent To Asphalt.
3					Pipe Joint Near Centreline Remains Open.	Repair / Reseal Utility Pipe Insulation Joint.
4					Sidewalk Has Settlement At Both Ends Creating Elevation Difference Between Approaches And Bridge Deck.	Consider Rebuilding Sidewalk Approaches.

## ENGINEER'S COMMENTS

This structure is in good condition with minor maintenance items required and repairs / resealing work required to attached utilities.



Photo #01. View Of Structure From East Approach.



Photo #02. View Of Structure From West Approach.





Photo #03. View Of Structure From Downstream East Bank.



Photo #04. View Of Structure From Upstream East Bank.





Photo #05. View Upstream.



Photo #06. View Downstream.





Photo #07. East Abutment Joint.



Photo #08. West Pier Joint.



Photo #09. West Abutment Joint.



Photo #10. Underside Of Box Girders And West Abutment.





Photo #11. Rip Rap On East Abutment.



Photo #12. East Pier.



Photo #13. Sanitary Force Main And Waterline From East Bank.



Photo #14. Waterline Near Mid-Span. Note: Missing Pipe Insulation Joint And Deterioration Of Insulation.





Photo #15. Utility Box At Downstream West Abutment. Note: Loose And Open Conduit.



Photo #16. Sidewalk From East Pathway Approach..





Photo #17 Sidewalk At West Wing Wall. Note: Damage To Wing Wall And Repositioned Rail Base.



Photo #18. West Pier.



**BRIDGE CONDITION SURVEY****Nicola River Pedestrian Bridge****City of Merritt**

---

Municipality:	City of Merritt
Structure:	Nicola River Pedestrian Bridge
Number:	5
Inspector(s):	Stephan Anderson CTech.
Inspection Date:	2015 Dec 1
Temperature:	- 8 Degrees Celsius

---

**GENERAL DESCRIPTION**

Location:	West End Of Quilchena Avenue At The Nicola River
Crossing Type:	River Crossing
Structure Type:	Vintage Railroad Plate Girder
Estimated Traffic:	Pedestrian Traffic
Load Rating:	No Restrictions Posted
Clearances:	No Restrictions Posted
Replacement Cost:	\$300,000.00

---



---

**BRIDGE CONFIGURATION**

Overall Length:	18m
Overall Width:	3.7m
Skew:	None
No. Of Spans:	One
Length Of Spans:	18m
No. Of Piers:	None
No. Of Abutments:	Two

---

**BRIDGE CROSS SECTION**

Sidewalk/Bicycle Path	
Number:	One
Width:	1.85m
Vehicle Lanes	
Number:	None
Width:	

---

**STRUCTURAL HISTORY**

## Original Construction

Engineer:	Not Available
Contractor:	Not Available
Design Code:	Not Available
Design Vehicle:	Not Available
Year:	Not Available

## Regular Load Analysis

Rating:	Not Reviewed
Engineer:	
Year:	

## Clause 12 Load Analysis

Rating:	Not Reviewed
Engineer:	
Year:	

---

## ROADWAY INSPECTION

	Observations	Recommendations
Bridge Rail Type: Condition:	None	
Bridge Parapet Type: Condition:	None.	
Pedestrian Rail Type: Height: Condition:	Timber Posts And Railing With Supplemantary Chain Link Inbetween Topped With Galvanized Steel Pipe Handrail. 1.5m (Approximately). Good. Two Lengths Of Pipe Handrail Are Missing At South End Both Sides.	Replace Pipe Handrail.
Sidewalk/Bicycle Path Location: Type: Condition:	Centreline. Timber Plank Decking. Good. Debris Collecting In Between Deck Planks At Centreline Due To Underlying Stringer Top Surface. Bebris Will Hold In Moisture And Shorten The Lifespan Of The Timber Decking.	Remove Accumulated Debris To Facilitate Air Movement Around Timber Decking.
Curb Location: Type: Condition:	None.	
Wearing Surface Type: Condition:	None.	

End Joints Type: Condition:	None.	
Intermediate Fixed Joints Location: Type: Condition:	None.	
Intermediate Expansion Joints Location: Type: Condition:	None.	
Deck Drains/Scuppers Type: Condition:	None.	



## SUPERSTRUCTURE INSPECTION

	Observations	Recommendations
Floor Beams Type: Condition:	Creosoted Timber Floor Beams. Good.	
Girders Type: Number: Depth: Condition:	Plate Girder. Two. 1700 Deep. Fair, Peeling Paint With Some Graffiti.	Repaint As Needed To Prevent Corrosion.
Diaphragms Location: Type: Condition:	At Plate Deck Beams. Steel Plate. Fair, Peeling Paint	Repaint As Needed To Prevent Corrosion.
Bearings Location: Type: Condition:	Abutments. Sliding And Fixed Not Accessible For Inspection.	

## ABUTMENT INSPECTION

	Observations	Recommendations
Bearing Pedestal Type: Condition:	CIP Concrete Beam Seat. Fair. Fair Condition Considering Age With Some Cracking.	
Ballast Wall Type: Condition:	CIP Concrete. Fair. Fair Condition Considering Age With Some Cracking And Spauling Of Surface.	
Base Type: Condition:	CIP Concrete. Not Observed, Under Water and Ice	
Foundation Type: Footing:	Timber Piles. Not Observed. Under Water and Ice.	
Wing Walls Type: Condition:	None.	

Slope Protection Location: Type: Condition:	Upstream And Downstream Of Abutments. Rip Rap With Vegetation. Poor. Slopes Under Snow And Ice At Time Of Inspection.	
Waterway Channel Alignment: Flow: Stability:	Fair. Alignment Is Skewed Approximetaly 30 Degrees. Moderate To Low At The Time Of Inspection. Fair. Channel Under Snow And Ice At Time Of Inspection.	

## APPROACH INSPECTION

	Observations	Recommendations
Alignment Horizontal: Vertical:	Curved With Good Sight Lines. Slight Slope.	
Guardrail Location: Type: Condition:	None.	
Barrier Location: Type: Condition:	None.	
Sidewalk/Bicycle Path Location: Type: Condition:	Centreline. Timber Plank Decking. Good.	
Curbs Location: Type: Condition:	None.	
Roadway Type: Condition:	None.	
Roadway End Joint Type: Condition:	None.	



Approach Slabs Type: Condition:	Asphalt On East Approach. Gravel On West Approach. East Approach Good. West Approach Fair With Some Settling Of Existing Gravel Trail At Timber Deck Planks.	Replace Material To Level Gravel Trail With Timber Deck Elevation.
Approach Embankment Type: Condition:	Existing Rail Grade. Good	
Drainage Type: Condition:	None. Surface Only.	
Abutment Fencing Type: Condition:	Flared Timber Posts And Railing With Supplemantary Chain Link Inbetween. Good.	

## LIGHTING, ELECTRICAL AND SIGN INSPECTION

	Observations	Recommendations
Lamp Standards Number: Type: Condition:	None.	
Wiring & Junctions Condition:	None.	
Signs Condition:	Rotary Club Plaque At East Approach In Good Condition. Timber Sign Attached To Upstream Side Of Bridge Girder Is Detached On The South End.	Repair Sign.

## UTILITIES INSPECTION

	Observations	Recommendations
Utilities Over Bridge BC Hydro: BC Tel: Other:	None. None. None.	
Utilities On Bridge BC Hydro: BC Tel: BC Gas: Water: Sanitary: Sewer: Other:	None. None. None. None. None. None. None.	
Utilities Adjacent To Bridge BC Hydro: BC Tel: BC Gas: Water: Sanitary Sewer: Storm Sewer: Other:	Unknown. Unknown. Unknown. Unknown. Unknown. Unknown. Unknown.	

## RECOMMENDED MAINTENANCE AND REPAIRS

Item	Approved		Completed		Description	Comments
	Initial	Date	Initial	Date		
1					Erosion At East Abutment. Not Identified This Inspection Due To Water Level And Ice Coverage Although May Remain.	Replace Gravel Materials At East Abutment And Armour With Rip Rap.
2					Damage To Handrail.	Replace Missing Steel Pipe Handrail At East Abutment.
3					Erosion At West Abutment. Not Identified This Inspection Due To Water Level And Ice Coverage Although May Remain.	Add Additional Rip Rap To Slope At West Abutment.
4					Debris Collecting In Between Deck Planks At Centreline Due To Underlying Stringer Top Surface. Debris Will Hold In Moisture And Shorten The Lifespan Of The Timber Decking.	Remove Accumulated Debris To Facilitate Air Movement Around Timber Decking.
5					Existing Coating Failed With Corrosion Of Steel Girders.	Consider Cleaning And Painting Steel Surfaces To Extend Service Life Of Structure.
6					Timber Sign Attached To Upstream Side Of Bridge Damaged.	Repair Sign

## ENGINEER'S COMMENTS

This structure is a vintage steel plate railroad bridge in relatively good condition for its current intended use as a pedestrian bridge. With some additional corrosion protection and slope protection at the east abutment this structure will likely last well into the future. Sign on upstream side of bridge is damaged.





Photo #01. View Of Structure From South Approach.



Photo #02. View Of Structure From North Approach.





Photo #03. View Of Structure From North Bank Upstream.



Photo #04. View Of Structure From South Bank Downstream.





Photo #05. North Abutment.



Photo #06. South Abutment.





Photo #07. South Abutment. Note Undermined Concrete Footing 2008 Inspection.



Photo #10. Detail Of South Abutment Undermining. Note Exposed Original Timber Piling 2008 Inspection.





Photo #11. Underside Of Bridge.



Photo #12. Upstream Plate Girder. Note: Peeling Paint.



Photo #13. View Upstream.



Photo #14. View Downstream.





Photo #15. Upstream Railing. Note: Missing Pipe Rail End Section.



Photo #16. Downstream Railing. Note: Missing Pipe Rail End Section.





Photo #17. Upstream Rail. Note: Railing Nuts And Washers Found Missing At South End.



Photo #18. Downstream Rail. Note: Nuts And Washers Missing.





---

Municipality:	City of Merritt
Structure:	Centennial Park Pedestrian Bridge
Number:	6
Inspector(s):	Stephan Anderson CTech.
Inspection Date:	2015 Dec 1
Temperature:	- 8 Degrees Celsius

---

**GENERAL DESCRIPTION**

Location:	At Centennial Park Across The Nicola River.
Crossing Type:	River Crossing
Structure Type:	Twin Steel Girder
Estimated Traffic:	Pedestrian Traffic
Load Rating:	No Restrictions Posted
Clearances:	No Restrictions Posted
Replacement Cost:	\$130,000.00

---

---

**BRIDGE CONFIGURATION**

Overall Length:	12m
Overall Width:	2.3m
Skew:	None
No. Of Spans:	One
Length Of Spans:	12m
No. Of Piers:	None
No. Of Abutments:	Two

---

**BRIDGE CROSS SECTION**

Sidewalk/Bicycle Path	
Number:	One
Width:	1.85m
Vehicle Lanes	
Number:	None
Width:	

---

**STRUCTURAL HISTORY**

## Original Construction

Engineer:	Not Available
Contractor:	Not Available
Design Code:	Not Available
Design Vehicle:	Not Available
Year:	Not Available

## Regular Load Analysis

Rating:	Not Reviewed
Engineer:	
Year:	

## Clause 12 Load Analysis

Rating:	Not Reviewed
Engineer:	
Year:	

---



## ROADWAY INSPECTION

	Observations	Recommendations
Bridge Rail Type: Condition:	None. Though Girder Acts As Bridge Rail.	
Bridge Parapet Type: Condition:	None. Though Girder Acts As Bridge Parapet.	
Pedestrian Rail Type: Height: Condition:	Upper Portion Of Steel Girders With Steel Pipe Handrail. 1.2m (Approximately). Good. Paint Peeling With Small Areas Of Corrosion	Paint Handrail
Sidewalk/Bicycle Path Location: Type: Condition:	Centreline. Timber Plank Decking. Fair Overall. Poor At North End Loose Plank At NW Corner. Wood Deck Screws Showing Signs Of Deterioration.	Replace Loose Decking. Consider Replacing Entire Deck With New 2 X 6 Decking.
Curb Location: Type: Condition:	None.	
Wearing Surface Type: Condition:	None.	

**BRIDGE CONDITION SURVEY****Centennial Park Pedestrian Bridge****City of Merritt**

End Joints Type: Condition:	None.	
Intermediate Fixed Joints Location: Type: Condition:	None.	
Intermediate Expansion Joints Location: Type: Condition:	None.	
Deck Drains/Scuppers Type: Condition:	None.	

## SUPERSTRUCTURE INSPECTION

	Observations	Recommendations
Deck Type: Condition:	Timber Plank Decking. As Above.	
Girders Type: Number: Depth: Condition:	Steel Girders two. 1000 Deep Good. Ends of Girders Buried.	Remove Material From Ends And Repaint As Required To Prevent Corrosion.
Floorbeams Location: Type: Condition:	Evenly Spaced Between Bridge Girders Steel Angle With Timber 4x4 Timber Insert For Deck Plank Attachment. Fair. Steel Angles Are Corroding.	Repaint As Required To Prevent Corrosion.
Bearings Location: Type: Condition:	Abutments. Loc Blocs Not Accessible For Inspection.	

## ABUTMENT INSPECTION

	Observations	Recommendations
Bearing Pedestal Type: Condition:	Loc Blocs Not Accessible For Inspection.	
Ballast Wall Type: Condition:	None.	
Base Type: Condition:	None.	
Foundation Type: Footing:	Unknown Not Accessible For Inspection.	
Wing Walls Type: Condition:	None.	



Slope Protection Location: Type: Condition:	Upstream And Downstream Of Abutments. Rip Rap With Vegetation. Fair. Some Rip Rap Present At Both Abutments With Soils And Grasses Mixed In, However Slopes Appear Sound. Material At West Abutment Should Be Armoured To Prevent Erosion.	Armour West Abutment With Smaller Rip Rap.
Waterway Channel Alignment: Flow: Stability:	Good. Moderately High Water With Ice At Time Of Inspection. Fair. Vegetation Is Stabalizing The Channel Slopes Other Than At The West Abutment As Mentioned Above.	Armour West Abutment With Smaller Rip Rap.

## APPROACH INSPECTION

	Observations	Recommendations
Alignment Horizontal: Vertical:	Straight With Good Sight Lines. Level.	
Guardrail Location: Type: Condition:	None.	
Barrier Location: Type: Condition:	None.	
Sidewalk/Bicycle Path Location: Type: Condition:	Approaches Well Graded Base Gravels. Good.	
Curbs Location: Type: Condition:	None.	

**BRIDGE CONDITION SURVEY****Centennial Park Pedestrian Bridge****City of Merritt**

Roadway Type: Condition:	None.	
Roadway End Joint Type: Condition:	None.	
Approach Slabs Type: Condition:	None.	
Approach Embankment Type: Condition:	None.	
Drainage Type: Condition:	None. Surface Only.	
Abutment Fencing Type: Condition:	None.	

## LIGHTING, ELECTRICAL AND SIGN INSPECTION

	Observations	Recommendations
Lamp Standards Number: Type: Condition:	None.	
Wiring & Junctions Condition:	None.	
Signs Condition:	None.	



## UTILITIES INSPECTION

	Observations	Recommendations
Utilities Over Bridge BC Hydro: BC Tel: Other:	None. None. None.	
Utilities On Bridge BC Hydro: BC Tel: BC Gas: Water: Sanitary: Sewer: Other:	None. None. None. Two Inch Diameter PVC Sprinkler Line None. None. None.	
Utilities Adjacent To Bridge BC Hydro: BC Tel: BC Gas: Water: Sanitary Sewer: Storm Sewer: Other:	Unknown. Unknown. Unknown. Unknown. Unknown. Unknown. Unknown.	

## RECOMMENDED MAINTENANCE AND REPAIRS

Item	Approved		Completed		Description	Comments
	Initial	Date	Initial	Date		
1					Failed Coating On Steel Girders And Handrails.	Clean And Paint Steel Surfaces To Maintain Corrosion Resistance When Required.
2					Steel Floor Beam Angles Are Corroding	Clean And Paint Steel Surfaces To Maintain Corrosion Resistance When Required.
2					Erosion At Abutments.	Replace Gravel Materials At West Abutment And Armour With Rip Rap.
3					One Deck Plank Found Loose And Most Deck Screws Deteriorated.	Repair Loose Plank And/Or Consider Replacing 2 X 6 Plank Decking.
4					Ends Of Bridge Girders Buried In Soil Material.	Remove Soil Materials To Prevent Corrosion Of Bridge Girder Ends.

## ENGINEER'S COMMENTS

This structure is in good condition, however will soon require a new 2 x 6 timber plank deck due to loose planks and deteriorating deck screws and will require minor maintenance to prevent corrosion and have smaller rip rap placed at the west abutment to prevent erosion of existing materials.



Photo #01. View Of Structure From North Approach.



Photo #02. View Of Structure From South Approach.





**Photo #03. View Of Structure From North Bank Downstream.**



**Photo #04. View Of Structure From South Bank Upstream.**





Photo #05. View Upstream.



Photo #06. View Downstream.





Photo #07. Bridge And Hand Railing.



Photo #08 Underside Of Deck And South Abutment.





Photo #09 South Abutment. Note Minimal Slope Protection.



Photo #10 North Abutment. Note Material Leaking Through Deck Plank Gaps.





Photo #11 North Deck. Note Gaps In Deck Planks.



Photo #12 North Abutment. Note End Of Deck Planks Buried And Deteriorated.





Photo #13 South Abutment. Note: Steel Girder Buried.



Photo #14 North Abutment. Note: Steel Girder Buried.





Photo #15 Upstream Handrail. Note: Corrosion.



Photo #16 Deck Underside. Note: Corrosion Of Steel Floorbeam.

